

Input file	A-T0	A-T1	A-T2	A-T3	A-T4	A-T5	B-Step1(T6)	B-Step2	B-Step3	B-Step4	B-T8
./hwrng-1G-4.bin	PASS	257/257	257/257	257/257	257/257	257/257	PASS	PASS	PASS	PASS	8.0042